



ESTIMATE TO:

Mcknight Crossing Church  
2515 S. McKnight Rd.  
[thunsaker@mcknightcrossings.org](mailto:thunsaker@mcknightcrossings.org)

**EST1083**

Date: Jan 4, 2024

#	Item	Unit Price	Qty	Total
01	<b>Repair And Resurface Baptismal Pool</b> Work scope includes repairing leaks and fiberglass work as needed to address any issues. Remove and repair failing paint on baptismal pool and refinish entire baptismal pool in blue coatings. A New Look Resurfacing will do extensive repairs to make baptismal pool look new.	\$4,265.00	1	\$4,265.00
			Subtotal	\$4,265.00
			<b>Grand Total</b>	<b>\$4,265.00</b>

Thank you!

Note:

Fiberglass over holes from piping that will be removed.

3 layers of fiberglass will be installed and a water proofing product will be installed to ensure 100% waterproofing.

All work will be covered under warranty for 1 year

Warranty will cover all workmanship and any leaks